

## ABSTRACT

Nanocomposites may be produced by mixing dispersions of polymers and  
5 dispersions of clay minerals. After mixing, the dispersions may be destabilized with the addition of appropriate compounds. The flocculated solid material exhibits characteristics of a nanocomposite, such as exfoliation of the clay mineral platelets as indicated by x-ray diffraction analysis.

10